



* Note: To avoid water ingress by capillary reaction, when the gap between the cladding & the sill tray down leg is less than 5mm the gap must be sealed.

Section Through Sill

Note:
Redway Developments Silltray must have stop ends (supplied) solvent fixed at each end of tray.

REDWAY DEVELOPMENTS LTD

Manufacturer's of 'The Sill Tray'
BRANZ Appraised No. 424 (2005)

SALES: P.O.Box 31 - 202, Christchurch 8030, NEW ZEALAND
TELEPHONE: 64 3 3585 775, FACSIMILE: 64 3 3589 529



PAGE 31 - WEATHERBOARD ON CAVITY ON CAVITY